

RECEIVED
CENTRAL FAX CENTER

FEB 21 2006

7721 Sunset Avenue
Newark, CA 94560
(510) 793-4744**Miller**INVESTMENT
CORPORATION

Fax (510) 742-

6686

Fax Cover Sheet

DATE	Feb 20, 2006
TO	U.S. PATENT OFFICE
CC	RON@GHZDATA.COM
FROM	RONALD B. MILLER
TOTAL PAGES (INCLUDING COVER SHEET)	5
FAX NUMBER	571-273-8300
SUBJECT	PAT App 10 601464

ATTN: D. Bell
Ishwar Patel

(1)



Miller Investments

RECEIVED
CENTRAL FAX CENTER

FEB 21 2006

Friday Feb 20 ~~January 24~~, 2006

COMMISSIONER FOR PATENTS
PO BOX 1450
Alexandria VA 22313-1450

Attn: Ishwar Patel, Examiner
Art Unit 2841
RE: 10/601/464
RE: Response to Office Action Summary 11/29/2005
RE: Notice of Non-Compliant Amendment sent on 12/29/05 by D Bell
RE: my Letter and amendment of December 26, 2005

Dear Mr Patel,

The Notice of Non-Compliant Amendment sent on 12/29/05 by D Bell
Amendment to the claims

- A. A complete listing of all the claims is not present.
- B. Each claim has not been provided with the proper status identifier.

EXCERPT FROM MY LETTER OF DECEMBER 26, 2005
Page 2 DETAILED ACTION paragraph 1.

PLEASE REMOVE

~~Please recognize that I am not a patent attorney, and that I have agreed to the withdrawal of claims 1, 4, 7, 13, 14, and 17 on the advice of the patent examiner, who has assured me that no one can use these methods of fabrication of this self same structure if the main patent claims are granted.~~

This paragraph above was a typographic error which was not the intent of the applicant.

PLEASE SUBSTITUTE IN ITS PLACE:

Claim 1 (Currently amended)

A printed circuit board PCB see figure 2 with internal (signal traces) on a thin dielectric layer (designated dielectric layer) suspended in air (conductor removed air dielectric) between two flat metal plates (top metal plate) and (bottom metal plate). Suspension in air of the dielectric layer is accomplished by indentation of the flat metal plates above and below the trace and a distance away from the edges, the width of this indentation being

7721 Sunset Avenue, Newark, California 94560 510.793.4744 Fax 510.742.6686

www.GHZDATA.com

2